
Top Secret



INTELLIGENCE

Industrial Facilities (Non-Military)

Basic Imagery Interpretation Report

Major Electric Power Plants Honan Province, China

Top Secret

25X1

RCS	13/0011/7	ı
		25X1
DATE	, F <u>e</u> bruary	197 1
COPY	11/	
PAGES	7	

Approved For Release 2008/10/06: CIA-RDP79T00909A000900010039-5



	Ar	proved For Relea	se 2008/10/06	: CIA-RDP79T	700909A00090	0010039-
--	----	------------------	---------------	--------------	--------------	----------

RCS - 13/0011/71

25X1


CENTRAL INTELLIGENCE AGENCY Directorate of Intelligence Imagery Analysis Service

ABSTRACT

This report, based on late 1969 and 1970 photography, updates previous basic reporting on four of the major electric power plants in Honan Province, east-central China. The cut-off date for information is September 1970.

No changes were observed at any of the plants since the previous report. The status of construction at the An-yang Thermal Power Plant could not be determined because of smoke obscuring the boilerhouses.

Three of the plants were operating on the latest coverage. The San-men Hsia Hydro Power Plant did not appear to be operating.



TOP SECRET RUFF

		TOP SECRET RU	JFF		
		,	5		
		INTRODUCTION			
This in Honan	report covers the Province (see Fig	ne following four gure I).	major elec	tric power p	lants
	I. An-yang Thei	rmal Power Plant.			
	2. Cheng-chou H	Heat and Thermal F	Power Plant	•	
	3. Lo-yang Thei	rmal Power Plant. a Hydro Power Plan		San-men Gorge	ə.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorgo	э.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorgo	e.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorg	e.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorg	e.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorg	е.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorg	e.
	3. Lo-yang Thei	rmai Power Plant.		San-men Gorg	e.
Requireme	3. Lo-yang Them 4. San-men Hsia	rmai Power Plant.		San-men Gorg	e.
Requireme COMIR	3. Lo-yang Them 4. San-men Hsia	rmai Power Plant.		San-men Gorg	е.
COMIR	3. Lo-yang Them 4. San-men Hsia	rmal Power Plant. a Hydro Power Plan		San-men Gorg	e.
COMIR Suppo	3. Lo-yang Them 4. San-men Hsia At NOI The Number 42194	rmal Power Plant. a Hydro Power Plan		San-men Gorgo	e.
COMIR Suppo Document	3. Lo-yang Them 4. San-men Hsia At NOI Thumber 42194 Reference	rmal Power Plant. a Hydro Power Plan	nt and Dam		
COMIR Suppo	3. Lo-yang Them 4. San-men Hsia A. San-men Hsia EX NOI TH Number 42194 Reference RCS -13/0020/70,	rmal Power Plant. a Hydro Power Plan 4 Major Electric Po	nt and Dam	Honan Provin	
COMIR Suppo Document	3. Lo-yang Them 4. San-men Hsia At NOI Thumber 42194 Reference	rmal Power Plant. a Hydro Power Plan 4 Major Electric Po	nt and Dam	Honan Provin	
COMIR Suppo Document CIA.	3. Lo-yang Them 4. San-men Hsia A. San-men Hsia EX NOI TH Number 42194 Reference RCS -13/0020/70,	rmal Power Plant. a Hydro Power Plan 4 Major Electric Po	nt and Dam	Honan Provin	
COMIR Suppo Document CIA.	3. Lo-yang Them 4. San-men Hsia X NOI T Number 42194 Reference RCS -13/0020/70, February 1970,	rmal Power Plant. a Hydro Power Plan 4 Major Electric Po	nt and Dam	Honan Provin	

25X1

25X1

				•	
······································				Ÿ	
INSTALLATION OR AC	TIVITY NAME			COUNTRY	_
An-yang Therma	al Power Plant			СН	
JTM COORDINATES	GEOGRAPHIC COORDINA			<u> </u>	2
50SKR540005 MAP REFERENCE	36-07-30N 14-16	5-20L			
15th RTS. USA (SE	CRET	3heet M038	82 - 24HL. 3rd ed. Aua 67.	Scale 1.200 000	
ATEST IMAGERY USE	<u>D</u>		NEGATION DATE (IT required)		
					2
			NA NA		-
The nlant	ina in	~ban			
The plant issuing from t	was operating in he center stack.	December	1969, as indicated by	heavy smoke	
The plant issuing from t	was operating in he center stack.	ı December	1969, as indicated by	heavy smoke	
The plant issuing from t	was operating in he center stack.	December	1969, as indicated by	heavy smoke	
The plant issuing from t	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant issuing from t	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant ssuing from t	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	December	1969, as indicated by	heavy smoke	
The plant	was operating in he center stack.	n December	1969, as indicated by	heavy smoke	2

NSTALLATION OR AC	TIVITY NAME		COUNTRY
Cheng-chou Heat	t and Thermal Power Plant		СН
JTM COORDINATES	GEOGRAPHIC COORDINATES		
19SGJ364496	34-46-08N 13-35-49E		
MAP REFERENCE			
5th RTS. USAT	TC, <u>Series 200, Sheet 03</u> 85	5-9HL, 2nd ed, Nov 63, Sc	ale 1:200,000
	CRET		4
ATEST IMAGERY USE	ED	NEGATION DATE (If required)	
		N/A	
		NA	
since October I report. The plant	s have been observed at Ch 1969, the date of the late was operating in July 197 ack and light vapor from toperation.	est photography used in t 70. Heavy smoke was eman	he previous mating from



STALLATION OR AC	CTIVITY NAMI	Ε	COUNTRY
an-men Hsia H	ydro Powe	r Plant and Dam	San-men Gorge CH
TM COORDINATES PSEJ 3 I 9545	GEOGRAPH	IC COORDINATES 6N 111-20-57E	
	ATC, Seri ECRET√	es 200, Sheet MO	385-7HL, 2nd ed, Sep 68, Scale I:200,000
ATEST IMAGERY USI	ED		NEGATION DATE (If required)
]	NA
am since Octob revious repor- The plant as impounded b	per 1969, t. did not pehind th	en observed at Sa the date of the appear to be oper e dam. No turbu	ESCRIPTION an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water lence was observed in the tailrace
The plant impounded to the state of the stat	did not openind the deposition of the port, the of the position of the port,	en observed at Sa the date of the appear to be open e dam. No turbu t had nearly bloc e tailrace on pho e only activity s gantry cranes whi	an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water
The plant is impounded to the plant is impounded to the plant is last observations reprevious representation repr	did not openind the deposition of the port, the of the position of the port,	en observed at Sa the date of the appear to be open e dam. No turbu t had nearly bloc e tailrace on pho e only activity s gantry cranes whi	an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water lence was observed in the tailrace cked the tailrace. Turbulence otography of September 1966. Since seen at the dam has been changes
The plant is impounded to the plant is impounded to the plant is last observations reprevious representation repr	did not openind the deposition of the port, the of the position of the port,	en observed at Sa the date of the appear to be open e dam. No turbu t had nearly bloc e tailrace on pho e only activity s gantry cranes whi	an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water lence was observed in the tailrace cked the tailrace. Turbulence otography of September 1966. Since seen at the dam has been changes
m since Octobervious report The plant simpounded to a heavy si s last observe previous rethe position	did not openind the deposition of the port, the of the position of the port,	en observed at Sa the date of the appear to be open e dam. No turbu t had nearly bloc e tailrace on pho e only activity s gantry cranes whi	an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water lence was observed in the tailrace cked the tailrace. Turbulence otography of September 1966. Since seen at the dam has been changes
The plant is impounded to the plant is impounded to the plant is last observations reprevious representation repr	did not openind the deposition of the port, the of the position of the port,	en observed at Sa the date of the appear to be open e dam. No turbu t had nearly bloc e tailrace on pho e only activity s gantry cranes whi	an-men Hsia Hydro Power Plant and latest photography used in the rating in June 1970. Little water lence was observed in the tailrace cked the tailrace. Turbulence otography of September 1966. Since seen at the dam has been changes

-7-

25X1

TOP SECRET RUFF

Top Secret

Top Secret